

**PROGRAM FOR REPAIR OF BFP-OWNED EMERGENCY & SERVICE VEHICLES FOR  
CY 2019**

as of 24 June 2019

END-USER	MAKE/TYPE	PLATE NO.	ENGINE NO.	PROJECT COST
----------	-----------	-----------	------------	--------------

**FUND CODE 831**

<b>REGION 1</b>					
1	Umingan FS, Pangasinan	Nissan	SEC-837	6BD1-690483	PHP 541,420.00
2	Dagupan City FS, Pangasinan	Isuzu Morita	SEC-466	6BD1-321308	PHP 568,491.00
3	Dagupan City FS, Pangasinan	Hyundai Daeyang	SGC-971	D6BR3048726	PHP 569,106.25
4	Dingras FS, Ilocos Norte	FMC Ford Roughneck	SEC-728	345300	PHP 558,760.00
<b>&gt;&gt;&gt;Sub-total</b>					<b>PHP 2,237,777.25</b>
<b>REGION 2</b>					
1	Jones FS, Isabela	Nissan FT	SLF-932	FE6011744B	PHP 299,706.60
2	Gonzaga FS, Cagayan	Isuzu Forward	SKS-401	6HH1-277239	PHP 182,773.08
3	Sta. Ana FS, Cagayan	Kia FT	For Reg't	SF-157350	PHP 207,156.92
4	Tumauini FS, Isabela	Isuzu Morita	22801	6BG1683668	PHP 329,915.15
5	Naguilian FS, Isabela	FMC Roughneck	SBM-139	1466916D15254019	PHP 319,202.57
6	Quirino FS, Isabela	Isuzu Forward	PDO-189	6HL1-304049	PHP 366,216.27
7	Sanchez Mira FS, Cagayan	FMC Roughneck	SEF-916	6D15-336769	PHP 333,040.79
<b>&gt;&gt;&gt;Sub-total</b>					<b>PHP 2,038,011.38</b>
<b>REGION 3</b>					
1	Dipaculao FS, Aurora	Foton Hurricane FT	SJJ-255	606G13823	PHP 339,465.00
2	Bagac FS, Bataan	Ford 800 Roughneck	SEC-737	8PA1-921822C	PHP 612,189.09
3	Paombong FS, Bulacan	Nissan Pumper	SEC-812	FE6-049629B	PHP 326,512.07
4	Baliuag FS, Bulacan	Isuzu Morita	No Plate No.	6BD1-316383	PHP 439,754.37
5	Talavera FS, Nueva Ecija	Isuzu Morita	SJJ-227	6BD1-326276	PHP 607,936.99
6	Macabebe FS, Pampanga	Hyundai Dong-a	SFW-764	8058400035	PHP 543,022.31
7	San Simon FS, Pampanga	Kia FT	SKX-324	K6-012170	PHP 834,635.56
8	Sto. Tomas FS, Pampanga	Hyundai Dong-a	SJB-539	80581000676BB1	PHP 725,263.77
<b>&gt;&gt;&gt;Sub-total</b>					<b>PHP 4,428,779.16</b>
<b>REGION 4-A</b>					
1	NFTI, Calamba, Laguna	Jiangte FT	No Plate No.	78225763	PHP 26,500.00
2	NFTI, Calamba, Laguna	Isuzu Anos	NUQ-724	4HG1764455P	PHP 45,000.00
<b>&gt;&gt;&gt;Sub-total</b>					<b>PHP 71,500.00</b>
<b>REGION 4-B</b>					
1	San Teodoro FS, Oriental Mindoro	Jiangte FT	No Plate No.	78234399	PHP 123,450.00
2	Alcantara FS, Romblon	Mitsubishi Canter	RMB-840	4D35-EG2332	PHP 232,300.00